



LASER INJURY GUIDE

IF INJURED BY A LASER, FOLLOW THESE STEPS:

1	Stop all work in the lab
2	Shut down all lasers in the lab (do not resume until LSO approves)
3	<p>Seek Medical Attention as soon as possible.</p> <p>Have a co-worker call for help and give assistance.</p> <ul style="list-style-type: none">• Severe injuries such as total loss of vision, bleeding from the eye, 2nd or 3rd degree burns to the eye area or face CALL 911 to request transport to the nearest hospital emergency room.• Exposures not resulting in severe injury, contact the HealthPoint Occupational Health Program to determine your next steps for medical treatment.
4	Do not alter the laser setup (this allows analysis to find the cause of the accident, and to take corrective action to prevent a re-occurrence)
5	Notify the laser user's work lead or supervisor and the UT Austin Laser Safety Officer

EMERGENCY CONTACTS

<i>Contact</i>	<i>Phone</i>	<i>After Hours</i>
HealthPoint	512-471-4647	Press 1 for on-call contact
Laser Safety Officer	512-471-3511	512-875-0911 (pager)
UT Police	512-471-4441 / 911	512-471-4441 / 911

YOUR LOCATION INFORMATION

Building: _____	Room Number: _____
Address: _____	
PI: _____	Lab Phone: _____