Radiation/Contamination Survey Record

Date	Time	Instrument Model #	Instrument Serial #	Bkgd (dpm)	Survey Description (location of survey, items surveyed, etc.	Survey Results (dpm/100 cm^2)	Signature
01Apr05	0900	Ludlum 3	198712	50	Direct survey of MBB 3.101 north bench rad area near sink.	Nothing above background	*Radiation Worker*
01Apr05	1430	LS6500	707326	86	Smear samples of inside of Beckman centrifuge in WEL 4.265	See attached LSC printout	Super Technician